Damage Control plotting drill #1

Drill # 1

1 Time: 0900; From OSL to Rep 3

smoke reported, black, compartment 2-328-2-L

2 Time: 0905; From OSL to Rep 3

Class "A" fire, compartment 2-328-0-Q

3 Time: 0911; From OSL to Rep 3

Request fire boundaries,

Primary 328, 368

Secondary 292, 418

Drill # 1

4 Time: 0913; From OSL to Rep 3

Request magazine sprinkler system be manned, compartment 2-328-0-Q

5 Time: 0917; From OSL to Rep 3

Electrical power isolated, compartment 2-328-0-Q

6 Time: 0918; From Rep 3 to OSL

Fire boundaries ordered,

Primary 328, 368

Secondary 292, 418

Drill # 1

7 Time: 0920; From OSL to Rep 3

Shoring required at scene, compartment 2-368-01-L,

frame 368, Remarks-QAWTD 2-386-2 (I type)

8 Time: 0924; From OSL to Rep 3

Compartment Demolished, 2-368-1-A

9 Time: 0928; From OSL to Rep 3

Fire boundaries set, compartment 2-328-0-Q

Primary 328, 368

Secondary 292, 418

Drill # 1

10 Time: 0931; From OSL to Rep 3

Class "A" fire contained, compartment 2-328-0-Q

11 Time: 0940; From OSL to Rep 3

6 inch Hole reported, compartment 2-328-2-L,

at frame 365, center of hole is 4 foot off the deck,

port side

12 Time: 0951; From OSL to Rep 3

Class "A" fire out, compartment 2-328-0-Q

Drill # 1

13 Time: 0956; From OSL to Rep 3

Ruptured firemain reported, compartment

2-368-01-L, frame 388, on the centerline overhead

14 Time: 1001; From OSL to Rep 3

Shoring in progress, (Steel) compartment 2-368-01-L,

Remarks: QAWTD 2-386-2

15 Time: 1006; From OSL to Rep 3

Class "A" fire reflash watch set, compartment 2-328-0-Q


STOP

Drill # 1

16 Time: 1012; From OSL to Rep 3

Ruptured firemain isolated, COV 2-366-2, compartment 2-328-2-L, at frame 388

17 Time: 1018; From OSL to Rep 3

Compartment cleared, 2-368-1-A.

18 Time: 1023; From OSL to Rep 3

Shoring complete, (I Type)

Remarks: QAWTD 2-386-2

Drill #1

19 Time: 1028; From OSL to Rep 3

Class "A" fire overhauled, compartment 2-328-0-Q

20 Time: 1033; From OSL to Rep 3

6 inch hole, plugging in progress, compartment 2-328-2-L

21 Time: 1037; From OSL to Rep 3

Ruptured firemain bypassed, COV 2-361-2 open, compartment 2-368-01-L

Drill # 1

22 Time: 1040; From OSL to Rep 3

Smoke cleared, black, compartment 2-328-2-L,

Ram Fan (2000 CFM, 125 PSI).

23 Time: 1055; From OSL to Rep 3

Smoke cleared, black, compartment 2-328-0-Q,

Ram Fan (2000 CFM, 125 PSI).

24 Time: 1103; From OSL to Rep 3

Compartment 2-328-0-Q checked for safe entry

- Oxygen----------safe, + O
- Explosive test-------safe, - E
- Toxic gas test-------safe, - T

Drill # 1

25 Time: 1110; From OSL to Rep 3

No apparent electrical damage, compartment 2-328-0-Q

26 Time: 1115; From OSL to Rep 3

Compartment 2-328-2-L checked for safe entry

- Oxygen----------safe, + O
- Explosive test-------safe, - E
- Toxic gas test-------safe, - T

27 Time: 1118; From OSL to Rep 3

Electrical power restored, compartment 2-328-0-Q

Drill # 1

28 Time: 1123; From OSL to Rep 3

No apparent damage surrounding areas, compartment

2-328-0-Q

LAST MESSAGE!!

Message
1

S

Black

time 0900

From

To

1

	R2
	R3
	R5
	DCC
X	Scene leader
	Bridge
	Investigators

Location 2-328-2-L

Frame

Remarks:



Message
2

A

time 0905 # 2

From To

R2
R3 X
R5
DCC
X Scene leader
Bridge
Investigators

Location 2-328-0-Q
Frame
Remarks:



Message
3

time 0911 # 3

From To

R2
R3 X
R5
DCC
X Scene leader
Bridge
Investigators

Location
Frame
Remarks: Request fire boundaries
pri 328, 368 sec 292, 418



Message
4

time 0913 # 4

From To

R2
R3 X
R5
DCC
X Scene leader
Bridge
Investigators

Location 2-328-0-Q
Frame Request mag sprinkler
Remarks: system be manned

OVHD/FWD

PORT STBD

DECK/AFT

Message
5

time 0917 # 5

From

To

	R2
	R3 X
	R5
	DCC
X	Scene leader
	Bridge
	Investigators

Location 2-328-0-Q

Frame

Remarks:



Message
6

FB

S	P	P	S
2	3	3	4
9	2	6	1
2	8	8	8

time 0918 # 6

From

To

	R2	
X	R3	
	R5	
	DCC	
	Scene leader	X
	Bridge	
	Investigators	

Location

Frame

Remarks:



Message
7

Pant

Frame 368

time 0920 # 7

From To

R2
R3 X
R5
DCC
X Scene leader
Bridge
Investigators

Location 2-368-01-L

Frame

Remarks: QAWTD 2-386-2



Message
8

C/D

time 0924 # 8

From To

	R2	
	R3	X
	R5	
	DCC	
X	Scene leader	
	Bridge	
	Investigators	

Location 2-368-1-A

Frame

Remarks:



Message
9

time 0928

9

From

To

R2
R3
R5
DCC
Scene leader
Bridge
Investigators

X

X

2-328-0-Q

FB

S P P S
2 3 3 4
9 2 6 1
2 8 8 8

Location
Frame
Remarks:



Message
10

time 0931 # 10

From

To

From	To
	R2
	R3
	R5
	DCC
X	Scene leader
	Bridge
	Investigators

A

Location 2-328-0-Q

Frame

Remarks:



Message
11

H

6” FR 365
4’ off deck

time 0940 # 11

From

To

R2
R3
R5
DCC
Scene leader
Bridge
Investigators

X

X

Location 2-328-2-L

Frame

Remarks:



Message
12

time 0951 # 12

From

To

	R2
	R3 X
	R5
	DCC
X	Scene leader
	Bridge
	Investigators

Location 2-328-0-Q

Frame

Remarks:



Message
13

R
FM
FR 388

time 0956 # 13

From

To

	R2	
	R3	X
	R5	
	DCC	
X	Scene leader	
	Bridge	
	Investigators	

Location 2-368-01-L

Frame

Remarks Center line, OVHD



Message
14

time 1001 # 14

From To

	R2	
	R3	X
	R5	
	DCC	
X	Scene leader	
	Bridge	
	Investigators	

Location 2-368-01-L

Frame

Remarks QAWTD 2-386-2

I-type pant



Message
15


time 1006
15
From
To
R2
R3
X
R5
DCC
X
Scene leader
Bridge
Investigators
Location
2-328-0-Q
Frame
Remarks:
A
OVHD/FWD
PORT
STBD
DECK/AFT

Message
16

time 1012 # 16

From To

R

FM

FR 388

	R2
	R3 X
	R5
	DCC
X	Scene leader
	Bridge
	Investigators

Location 2-366-2-L

Frame

Remarks COV 2-366-2



Message
17

time 1018 # 17

From To

From	To
	R2
	R3 X
	R5
	DCC
X	Scene leader
	Bridge
	Investigators

Location 2-368-1-A

Frame

Remarks:

C/D











Message
18

time 1023 # 18

From To

R2
R3 X
R5
DCC
X Scene leader
Bridge
Investigators

Location
Frame
Remarks QAWTD 2-386-2



Message
19

time 1028 # 19

From To

	R2
	R3 X
	R5
	DCC
X	Scene leader
	Bridge
	Investigators

Location 2-328-0-Q

Frame

Remarks:



Message
20

time 1033 # 20

From To

H

6” FR 365
4’ off deck

R2
R3 X
R5
DCC
Scene leader X
Bridge
Investigators

Location 2-328-2-L
Frame
Remarks:




time 1037
21
From
To
R2
R3
X
R5
DCC
X
Scene leader
Bridge
Investigators
R
Location 2-368-01-L
FM
FR 388
Frame
Remarks COV 2-361-2 open
Message
21
OVHD/FWD
PORT
STBD
DECK/AFT


time 1040
22
From
To
R2
R3
R5
DCC
Scene leader
Bridge
Investigators
X
X
Location
2-328-2-L
Frame
Remarks:
Ram fan
S
Black
Message
22
OVHD/FWD
PORT
STBD
DECK/AFT

Message
23

time 1055 # 23

From

To

R2
R3 X
R5
DCC
X Scene leader
Bridge
Investigators

Location 2-328-0-Q
Frame
Remarks:

Ram fan
S
Black




time 1103
24
From
To
R2
R3
R5
DCC
Scene leader
Bridge
Investigators
X
X
Location
2-328-0-Q
Frame
Remarks:
Message
24
Black
OVHD/FWD
PORT
STBD
DECK/AFT
Ram fan
S
+o
-E
-T

Message
25

NAED

time 1110
From

25

To

	R2
	R3
	R5
	DCC
X	Scene leader
	Bridge
	Investigators

X

Location 2-328-2-L
Frame
Remarks:



Message
26

time 1115
From

26

To

R2
R3
R5
DCC
Scene leader
Bridge
Investigators

X

X

Location 2-328-2-L
Frame
Remarks:





Message
27


time 1118
27
From
To
R2
R3
X
R5
DCC
X
Scene leader
Bridge
Investigators
Location
2-328-0-Q
Frame
Remarks:
E
OVHD/FWD
PORT
STBD
DECK/AFT

Message
28

NAP

time 1123 # 28

From To

	R2
	R3 X
	R5
	DCC
X	Scene leader
	Bridge
	Investigators

Location 2-328-0-Q

Frame

Remarks: Last message